F/G. 1




FIG. 3A







FIG. 3B



F/G. 3C



Best Available Copy



Best Available Copy

DESCRIPTION OF REFERENCE NUMERALS

- 1 · · · · die
- 1a ···· three-dimensionally curved surface part of the die
- 1' ···· die coated with a photoresist
- 1" ···· etching-finished die
- 2 ···· photomask
- 2' ···· mold-finished photomask
- 3 ···· far-infrared ray heater
- 4 ···· die for vacuum mold
- 11, 13, 13 ···· photomasks
- 20 ···· die coated with a photoresist
- 20a ···· seam on die surface